





ASR3(APR-3)

Voltage	3ΦAC380/AC415V 50/60HZ
Function	To prevent the reversal of three-phase induction motor, add breakthrough absorber to prevent excessive high voltage, which can effectively protect the load.
Contact	SPDT 5A/220VAC Under over 20% protective function
Operating temperature	-10°C to 55°C
Humidity	48 to 85% RH




Outline dimension



ASV-4

Voltage	3ΦAC380/AC415V 50/60HZ
Function	To prevent the reversal of three-phase induction motor, add breakthrough absorber to prevent excessive high voltage, which can effectively protect the load.
Contact	SPDT 5A/220VAC Under over 20% protective function
Operating temperature	-10°C to 55°C
Humidity	48 to 85% RH

Outline dimension



ASM-170

Voltage	3ΦAC380/AC380V Ac415 50/60HZ
Function	To prevent the reversal of three-phase induction motor, add breakthrough absorber to prevent excessive high voltage, which can effectively protect the load.
Contact	SPDT 5A/220VAC Under over 20% protective function
Operating temperature	-10°C to 55°C
Humidity	48 to 85% RH

Outline dimension

